




PERFECTION
Lens Series

ANTI-FATIGUE CENTRATION CHART



ADD CODES

0.50 = **05**
0.75 = **07**
1.00 = **10**

ANTI-FATIGUE MARKINGS

AP = Anti-Fatigue
APA = Anti-Fatigue Accuracy

INDEX MARKINGS

1.5 = **5** 1.59 = **9**
1.53 = **3** 1.6 = **6**
1.58 = **8** 1.67 = **7**
1.74 = **4**



CR SURFACING
Laboratories