




PERFECTION
Lens Series

TASK & DEVICE CENTRATION CHART



ADD CODES

0.75 = 07	2.25 = 22
1.00 = 10	2.50 = 25
1.25 = 12	2.75 = 27
1.50 = 15	3.00 = 30
1.75 = 17	3.25 = 32
2.00 = 20	3.50 = 35

TASK & DEVICE MARKINGS

T	= Task
TA	= Task Accuracy
D	= Device
DA	= Device Accuracy

INDEX MARKINGS

1.5 = 5	1.59 = 9
1.53 = 3	1.6 = 6
1.58 = 8	1.67 = 7
	1.74 = 4



CR SURFACING
Laboratories