

Perfection Everyday, EveryDay Wide, Digital, Anti-Fatigue and all Accuracy designs



	Clear	Tinted	Photochromatic	Special Photochromatic	Polarised	Special Polarised	Hardcoat	Satin UV	Satin Blue
1.74	✓		✓		✓		✓	✓	✓
1.67	✓		✓	Transitions® XtrActive	✓		✓	✓	✓
1.6	✓		✓		✓		✓	✓	✓
1.59	✓		✓	Transitions® XtrActive	✓	Drivewear, Graduated	✓	✓	✓
1.58	✓	✓					✓	✓	✓
1.53	✓		✓	Transitions® XtrActive, Vantage	✓	Drivewear	✓	✓	✓
1.5	✓	✓	✓	Transitions® Style, XtrActive, Vantage	✓	Drivewear, Infinite	✓	✓	✓

Perfection Task, Device, and all Accuracy designs

	Clear	Tinted	Photochromatic	Special Photochromatic	Polarised	Hardcoat	Satin UV	Satin Blue
1.74	✓		✓		✓	✓	✓	✓
1.67	✓		✓	Transitions® XtrActive	✓	✓	✓	✓
1.6	✓		✓		✓	✓	✓	✓
1.59	✓		✓	Transitions® XtrActive	✓	✓	✓	✓
1.58	✓	✓				✓	✓	✓
1.53	✓		✓	Transitions® XtrActive, Vantage	✓	✓	✓	✓
1.5	✓	✓	✓	Transitions® Style, XtrActive, Vantage	✓	✓	✓	✓

EP1 Freeform Progressive



	Clear	Tinted	Photochromatic	Polarised	Hardcoat	Satin UV	Satin Blue
1.74							
1.67							
1.6	✓		✓	✓	✓	✓	✓
1.59	✓		✓	✓	✓	✓	✓
1.58	✓	✓			✓	✓	✓
1.53							
1.5	✓	✓	✓	✓	✓	✓	✓

Signature IT Occupational

	Clear	Tinted	Photochromatic	Special Photochromatic	Polarised	Hardcoat	Satin UV	Satin Blue
1.74								
1.67	✓		✓	Transitions® XtrActive		✓	✓	✓
1.6	✓		✓		✓	✓	✓	✓
1.59								
1.58	✓	✓				✓	✓	✓
1.53								
1.5	✓	✓	✓	Transitions® XtrActive, Vantage	✓	✓	✓	✓